

Required	*Required*	*Required*	*Required*	*Required if no address*	*Required*	*Required*	*Required*	*Required*	*Required*	*Required*	*Required*	*Required*	*Required*	*Required*	*Required*		
Addresses				Unique Identifier	Gooseneck or Pigtail				System-Owned Portion *MHCs should list same materials for the riser in System-owned and Customer-owned columns.		Customer-Owned Portion *MHCs should list same materials for the riser in System-owned and Customer-owned columns.		Presence of Lead	Federal Classification	Status of Service Line	Access Denied	Notes
Street Address	City	State	Zip	Required if service line does not have a unique address	Basis of Material Classification	Service Line Material Classification	Basis of Material Classification	Service Line Material Classification	Basis of Material Classification	Service Line Material Classification	Was Material Ever Previously Connected to Lead (Columns G and H)?	*Auto-Calculated*	*Auto-Calculated*	If Applicable, Access Denial Date	Notes for Material Classification		
Water systems must provide addresses or another unique identifier for all service lines in their inventory.				Other unique identifier (parcel ID, service line ID, general location)	Select option from drop down list. If "Other," describe in the Notes (Column P).	Select option from drop down list. Select "Not Applicable" if the material type does not change between water main to curb stop.	Select option from drop down list. If "Other," describe in the Notes (Column P).	Select option from drop down list. If "Other," describe in the Notes (Column P).	Select option from drop down list. If "Other," describe in the Notes (Column P).	Select option from drop down list. If "Other," describe in the Notes (Column P).	Select option from drop down list.	The fields below auto-generate the classification of the entire service line as described by the EPA.	The fields below auto-generate the status of the service line.	Provide the date that access was denied for inspection. Documentation should be kept in water supply records.	This is an optional field that can provide additional detail about material classification.		
100 North Capitol Avenue	Lansing	Michigan	48933	Example: NE Corner	Physical verification	Copper	Records	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required	10/2/1873			
2920 Industrial Dr	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Other	Physical verification	Other	No	Non-Lead	Replacement Not Required		Ductile		
2669 Industrial Dr	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Other	Physical verification	Other	No	Non-Lead	Replacement Not Required		Ductile		
2549 Industrial Dr	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Other	Other	Other	No	Non-Lead	Replacement Not Required		Ductile		
2476 Industrial Dr	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2471 Industrial Dr	Grayling	Michigan	49738		Records	Not Applicable	Other	Other	Physical verification	Other	No	Non-Lead	Replacement Not Required		Ductile		
2410 Industrial Dr	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2342 Industrial Dr	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2306 Industrial Dr	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2288 Industrial Dr	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2268 Industrial Dr	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2210 Industrial Dr	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Other	Other	Other	No	Non-Lead	Replacement Not Required		Ductile		
2211 Industrial Dr	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Other	Physical verification	Other	No	Non-Lead	Replacement Not Required		Ductile		
2150 Industrial Dr	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2123 Industrial Dr	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2120 Industrial Dr	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2074 Industrial Dr	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
4602 Hanson St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
4603 Hanson St	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2310 Dupont St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2307 Dupont St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2323 Dupont St	Grayling	Michigan	49738		Records	Copper	Records	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2332 Dupont St	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
4606 Salling St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
4595 Salling St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2554 Industrial Dr	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
4564 Young St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
2562 EZ Built Dr	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
4388 M 72	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
602 Huron St	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
507 Huron St	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
503 Huron St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
501 Huron	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Customer self identification	Copper	Unknown	Non-Lead	Replacement Not Required				
500 Huron St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Plastic	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
402 Huron St	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
403 Huron St	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
307 Huron St	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
300 Huron St	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
301 Huron St	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Galvanized	Unknown	Galvanized Requiring Replacement	Requires Replacement				
230 Huron St	Grayling	Michigan	49738		Other	Not Applicable	Other	Other	Other	Other	No	Non-Lead	Replacement Not Required		private ductile pipe		
214 Huron St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
201 Huron St	Grayling	Michigan	49738		Records	Not Applicable	Records	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
407 Brink St	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
406 Brink St	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
405 Brink St	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
404 Brink St	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Assumption	Copper	Unknown	Non-Lead	Replacement Not Required				
402 Brink St	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Assumption	Copper	Unknown	Non-Lead	Replacement Not Required				
401 Brink St	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
308 Brink St	Grayling	Michigan	49738		Assumption	Not Applicable	Physical verification	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
307 Brink St	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Customer self identification	Copper	Unknown	Non-Lead	Replacement Not Required				
306 Brink St	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Customer self identification	Copper	Unknown	Non-Lead	Replacement Not Required				
301 Brink St	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Physical verification	Galvanized	Unknown	Galvanized Requiring Replacement	Requires Replacement				
209 Brink St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
206 Brink St	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Customer self identification	Copper	Unknown	Non-Lead	Replacement Not Required				
207 Brink St	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
205 Brink St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
203 Brink St	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
406 Mikado St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
405 Mikado St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
401 Mikado St	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
312 Mikado St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
311 Mikado St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	No	Non-Lead	Replacement Not Required				
310 Mikado St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
308 Mikado St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
307 Mikado St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Assumption	Copper	Unknown	Non-Lead	Replacement Not Required				
306 Mikado St	Grayling	Michigan	49738		Physical verification	Not Applicable	Physical verification	Copper	Physical verification	Copper	Unknown	Non-Lead	Replacement Not Required				
301 Mikado St	Grayling	Michigan	49738		Assumption	Not Applicable	Assumption	Copper	Assumption	Copper	Unknown	Non-Lead	Replacement Not Required				

